

Mains Power unit (MPU)
On top of machine.

High voltage card
(on its edge)

Front !

High voltage fuses
6 Amp 600 V
Very Fast !

